





Labnet AccuBlock
Digital Drybath and Fisher
Scientific Analog Models



Power



<u>SETUP</u>



OPERATION

Press the Start/Stop button to begin warm up. The red heating indicator light will come on and the display will change from reading the set temp to the current temp.

For manual models, there are 2 temperature settings to choose from. The knobs on either side can be used to adjust the temperature for their respective settings, enabling quick switching between temperatures.

When the heating period is complete, press the start/ stop key to deactivate the heating system.

Remove the heating block using the provided handle and allow to cool before handling. If a thermometer is being used in the block, remove it before moving the heating block.

Unload samples and replace the heating block in the dry bath.

Shut off main power when finished with the device.

HAZARDS



ELECTRICAL HAZARD

This equipment contains liquid near electrical connections.



HEAT HAZARD

This equipment produces heat and may cause burns.



INHALATION HAZARD

Because liquids are heated, dangerous fumes may be released.

PREVENTION



EYE PROTECTION

Wear safety glasses while operating.



PROTECTIVE GLOVES

Wear appropriate gloves for heat and chemical usage.



NON-SLIP, CLOSED SHOES

Wear non-slip, closed shoes to avoid spills.



READ MANUAL

Become familiar with this guide before operating.

For additional help contact the Lab
Space Manager